



n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB100@0 -37.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:55:41

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:54:27

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@105 -37.40dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:55:04

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB100@0 -36.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:57:39

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@0 -37.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:56:24

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@105 -36.66dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:57:01

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB128@0 -36.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:00:32

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.50dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:59:16

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@132 -37dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 20:59:54

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB128@0 -37.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:02:31

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.30dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:01:14

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@132 -36.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:01:53

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB128@0 -37.55dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:05:00

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:03:46

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@132 -37.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:04:25

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB160@0 -37.50dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:29:13

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB1@0 -37.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:27:55

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB1@159 -36.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 23:28:33

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB160@0 -37.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:23:33

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:22:15

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@159 -37.24dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:22:54

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB160@0 -36.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:25:34

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@0 -37.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:24:16

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@159 -36.70dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 14.AUG.2024 21:24:56

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB1@0 -36.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:27:24

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB1@215 -37.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:28:03

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB216@0 -37.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 14.AUG.2024 21:28:41

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 00:18:27

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@215 -37.79dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 00:19:08


n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB216@0 -37.18dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 00:19:50


n77_1

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -37.83dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:25:48

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -37.56dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:26:40

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -38.50dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:27:32

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:28:30

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -38.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:29:23

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -37.29dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 01:30:15

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:31:13

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -37.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:32:09

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -38.42dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:33:02

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.28dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:34:01

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:34:54

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:35:46

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:36:44

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -37.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:37:36

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -38.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:38:29

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:39:26

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:40:18

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:41:11

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:42:11

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -37.88dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:43:03

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -38.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:43:56

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:44:58

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -38.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:45:51

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -37.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:46:44

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -38.28dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:47:45

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -37.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:48:39

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -37.95dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:49:32

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -37.08dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:50:32

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -37.79dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:51:25

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -37.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 01:52:18

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:53:17

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -38.34dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:54:10

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -37.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:55:03

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:56:01

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -37.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:56:54

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -37.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:57:47

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -37.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:00:34

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -37.99dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:58:47

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -37.94dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 01:59:40

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -38.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:03:17

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:01:31

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -38.39dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:02:24

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -38.12dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:06:01

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -38.36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:04:15

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -38.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:05:08

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -38dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:08:51

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -38.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:07:04

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -37.50dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:07:57

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -38.23dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:11:37

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.14dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:09:49

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.52dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:10:43

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -38.12dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:14:22

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -38.04dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:12:35

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -38.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:13:29

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -34.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:17:11

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -38.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:15:23

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -38.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:16:17

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -38.66dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:19:57

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:18:10

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -38.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:19:04

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -37.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:22:43

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -38.08dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:20:55

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:21:49

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -38.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:25:32

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -37.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:23:44

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -38.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:24:38

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -38.01dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:28:19

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.35dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:26:31

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -37.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:27:25

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:31:04

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:29:16

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -37.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:30:10

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -37.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:32:05

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -38.29dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:33:00

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -38.08dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:33:55

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:34:54

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -38.21dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:35:49

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -37.62dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 02:36:44

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:37:44

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -38.27dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:38:38

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -37.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:39:33

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:40:33

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -37.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:41:28

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -38.55dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 02:42:22

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:43:20

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -37.80dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:44:15

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -37.28dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:45:09

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@0 -37.32dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:46:09

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -37.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:47:03

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -37.74dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 02:47:57

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.43dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 02:48:59

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -38.48dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 02:49:53


n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -37.56dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 02:50:48


n77_3

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -35.92dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 11:45:08

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@23 -35.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 11:45:55

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -36.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 15.AUG.2024 11:46:42

n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.85dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:47:33

n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@23 -35.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:48:20

n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB24@0 -34.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:49:08

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@0 -35.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:49:59

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@23 -35.80dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:50:46

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB24@0 -36.02dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:51:33

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.81dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:52:26

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@37 -35.88dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:53:14

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -35.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:54:02

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:54:57

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@37 -35.52dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:55:45

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB36@0 -35.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:56:32

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:57:24

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@37 -35.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:58:11

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB36@0 -35.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:58:59

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -35.38dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:00:01

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@50 -36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:00:49

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -36.18dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:01:37

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -36.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:02:34

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@50 -36.03dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:03:22

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB50@0 -35.39dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:04:11

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@0 -35.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:05:10

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@50 -36.08dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:06:00

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB50@0 -35.86dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:06:49