



n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -35.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:07:46

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@77 -35.62dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:08:37

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -35.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:09:25

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:10:19

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@77 -35.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:11:08

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB75@0 -35.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 12:11:58

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@0 -36dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:12:52

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@77 -35.77dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:13:41

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB75@0 -35.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:14:31

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -35.95dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:17:08

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -35.92dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:15:28

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -35.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:16:18

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB100@0 -35.41dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:19:46

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:18:07

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@105 -35.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:18:56

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB100@0 -35.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:22:23

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@0 -35.29dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:20:44

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@105 -35.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:21:34

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -35.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:25:00

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -35.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:23:20

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -35.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:24:10

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB128@0 -35.78dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:36:37

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:34:59

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@132 -35.61dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:35:48

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0 -35.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:39:10

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@0 -35.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:37:32

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132 -35.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:38:21

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -35.56dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:41:45

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -35.80dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:40:06

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -36.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 12:40:56

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0 -35.65dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:06:16

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.52dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:04:35

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@161 -34.79dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:05:26

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -35.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:08:57

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@0 -35.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:07:18

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -35.53dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:08:07

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -36.12dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:11:36

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -35.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:09:54

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -35.88dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:10:44

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0 -36.15dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:14:10

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:12:30

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@188 -35.67dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:13:20

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -35.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:16:46

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@0 -36.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:15:04

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -35.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:15:55

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -35.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:17:43

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -35.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:18:33

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -35.84dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:19:24

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.46dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:20:18

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@216 -36.01dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:21:09

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0 -35.31dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:21:59

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@0 -35.63dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:22:54

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -35.68dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:23:44

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -35.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:24:35

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -35.51dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:25:32

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -35.66dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:26:23

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -35.93dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:27:14

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.99dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:28:08

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@244 -35.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:28:59

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0 -35.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:29:50

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@0 -35.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:30:44

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -35.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:31:34

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -35.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:32:25

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:33:22

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -34.92dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:34:13

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -34.72dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:35:05

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -35.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:36:00

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@272 -36.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:36:50

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB270@0 -35.57dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:37:41

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@0 -35.64dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:38:37

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -35.76dBm



ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:39:29


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -35.73dBm



ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:40:20


n78_1

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -35.17dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:42:47

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -37.23dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:43:36

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -38.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:44:25

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:45:18

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -37.73dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:46:08

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -38.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 13:46:57

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -37.49dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:47:50

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -38.36dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:48:40

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -37.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:49:29

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:50:25

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.30dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:51:15

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.41dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 13:52:04

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.67dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:52:58

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -38.18dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:53:47

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -38.16dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:54:37

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.18dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:55:37

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -38.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:56:27

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.92dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:57:16

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -38.56dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:58:13

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -37.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:59:02

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -37.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 13:59:52

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.27dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 11:00:54

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -38.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 14:01:44

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -37.47dBm




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 15.AUG.2024 11:02:34

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -38.44dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:03:34

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -37.89dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:04:25

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -37.87dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:05:15

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -37.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:06:11

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -37.88dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:07:02

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -38.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:07:52

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 14:29:06

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -38.05dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:13:29

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -38.16dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 14:14:20

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -38.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:15:16

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -37.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 14:16:07

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -38.39dBm




ProjectNo.:2401V87404E-RF Tester:Kungumaster Liang
Date: 15.AUG.2024 11:16:57

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -38.39dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:19:38

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -38.11dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:17:56

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -38.19dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:18:47

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.69dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:31:43

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.63dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:30:01

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:30:52

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:34:29

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:32:46

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -38.25dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:33:38

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -37.98dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:37:10

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -37.75dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:35:27

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -38.22dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:36:19

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.96dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:39:49

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.24dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:38:06

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.02dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:38:58

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -38.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:42:32

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -37.54dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:40:46

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -37.76dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:41:38

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -38.13dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:45:18

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -38.33dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:43:33

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -37.90dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:44:27

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -37.87dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:48:00

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:46:16

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -38.14dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:47:08

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -38.48dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:50:44

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -38.26dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:48:59

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.71dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:49:52

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -38.45dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:53:31

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -37.86dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:51:45

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -38.20dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:52:39

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -37.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:56:14

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.91dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:54:29

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -38.09dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:55:22

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -37.60dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:58:59

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -37.94dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:57:12

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -38.10dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 11:58:06

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -37.97dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 14:59:58

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -37.59dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:00:53

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -37.61dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:01:45

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.51dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:02:43

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -38.08dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:03:38

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -37.66dBm



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 15.AUG.2024 15:04:30