



n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -46.766MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:09:44

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -43.647MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:44:38

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -47.335MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:20:11

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -39.758MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:46:11

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -47.274MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:48:26

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -42.832MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:47:44

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -47.520MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:49:57

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -40.316MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:49:14

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -47.289MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:51:44

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -46.961MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:51:00

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -47.413MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:53:26

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -45.742MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:52:43

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -31.405MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:54:18

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -46.709MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:55:03

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -29.697MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:55:56

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -46.761MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:56:45

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -32.243MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:57:42

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -45.866MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 11:58:27

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -26.942MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 14:59:17

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -46.559MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 15:00:02

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -29.940MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 15:01:06

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -42.671MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:22:24


n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -25.590MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 15:02:06


n77_3

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -47.207MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:11:26

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -47.377MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:12:00

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@23 -46.669MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:12:38

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB24@0 -46.561MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:13:11

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -45.869MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:13:51

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.341MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:14:29

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@37 -46.232MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:15:06

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB36@0 -46.657MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 23.AUG.2024 18:15:39

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -47.429MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 23.AUG.2024 18:16:19

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -47.488MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 23.AUG.2024 18:16:52

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@50 -46.826MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 23.AUG.2024 18:17:31

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB50@0 -46.133MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 24.AUG.2024 17:23:41

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -44.047MHz




ProjectNo.:2401V87404E-RF Tester:Kungfmaster Liang
Date: 23.AUG.2024 18:18:45

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -47.490MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:19:18

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@77 -43.264MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:19:57

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB75@0 -46.895MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:20:30

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -47.501MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:21:47

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -38.075MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:21:13

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB100@0 -46.983MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 23.AUG.2024 18:23:00

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@105 -38.579MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 18:22:26

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -47.627MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 18:24:17

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -43.276MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 18:23:42

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0 -46.872MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 18:25:30

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132 -44.539MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 23.AUG.2024 18:24:56

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -47.561MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 24.AUG.2024 17:27:48

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -35.831MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:26:23

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -46.72 dBm




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:31:39

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -35.862MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:30:51

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -47.498MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:36:00

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -42.814MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:33:00

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -46.839MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:39:26

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -39.652MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:37:17

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -24.388MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:40:38

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -44.132MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:41:28

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -21.974MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:44:05

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -46.023MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:45:24

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -23.999MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:47:22

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -44.819MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:48:22

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -19.981MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:49:45

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -45.842MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 17:51:24

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -22.453MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 18:02:30

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -36.765MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 11.SEP.2024 10:29:37


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -20.614MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 24.AUG.2024 18:03:53


n78_1

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -46.202MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 24.AUG.2024 18:05:21

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -42.035MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 28.AUG.2024 11:33:59

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -45.439MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 28.AUG.2024 11:36:52

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -41.405MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 28.AUG.2024 11:38:01

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -43.256MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 28.AUG.2024 11:42:01

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.255MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumastr Liang
Date: 28.AUG.2024 11:45:34

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -46.967MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:06:08

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.610MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:07:22

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -45.948MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 12:00:49

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -42.591MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:12:03

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -46.008MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:14:55

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -45.555MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:18:42

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -46.379MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:20:19

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -34.489MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:21:50

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -46.112MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:24:53

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -34.459MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:29:47

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -46.424MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:31:13

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -45.067MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:36:44

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -28.676MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:35:18

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -46.819MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:39:54

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -29.138MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:38:17

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -46.774MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:43:36

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -33.231MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 13:41:44

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -47.339MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:06:12