



n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -32.446MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 13:45:23

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -46.557MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 13:48:30

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -30.471MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 13:46:57

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -47.068MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 13:51:31

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -34.617MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 13:50:28

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -46.770MHz




ProjectNo.:2401V87404E-RF Tester:Kungfaster Liang
Date: 28.AUG.2024 11:08:26

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -39.079MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 14:07:16

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -47.052MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 11:10:24

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -39.431MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 14:09:39

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -22.451MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 11:11:17

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -42.788MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 14:12:03

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -23.500MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaister Liang
Date: 28.AUG.2024 11:13:01

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -46.217MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 14:15:52

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -20.955MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 14:20:30

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -42.754MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 14:22:23

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -23.069MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 14:24:40

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -46.420MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 16:28:55

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -19.329MHz




ProjectNo.:2401V87404E-RF Tester:Rungfmaster Liang
Date: 28.AUG.2024 14:29:22

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -40.622MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 16:24:19

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -21.153MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 14:31:45

n78_3
n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -42.745MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:39:13

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -45.277MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:41:34

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23 -41.744MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:42:23

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0 -45.108MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:43:50

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.586MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:45:01

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -45.905MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:46:32

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.856MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:48:10

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0 -45.505MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:49:04

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -43.740MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:50:28

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -46.598MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:51:11

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50 -44.705MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:52:07

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0 -45.759MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:53:07

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -34.347MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:55:10

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -46.628MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:56:39

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77 -34.368MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 09:58:01

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 -46.589MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:00:09

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -45.692MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:03:04

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -27.937MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:01:43

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -47.452MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:12:34

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -28.446MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:05:07

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -47.130MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:17:02

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -32.923MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:13:49

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 -47.053MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:20:15

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132 -33.640MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:18:02

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -47.112MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:23:00

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -32.364MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:22:11

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0 -47.226MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:25:19

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161 -34.727MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:24:21

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -47.394MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:29:01

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -38.209MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:27:08

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 -47.184MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:54:00

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188 -38.158MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:30:48

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -22.591MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:33:20

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -43.320MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:34:16

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216 -23.433MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:36:05

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0 -46.395MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:55:49

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -20.300MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:57:48

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -43.982MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 10:58:59

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244 -21.801MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:04:05

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0 -46.537MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:05:31

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -18.667MHz




ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:07:35

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -40.220MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:09:05

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -20.415MHz



ProjectNo.:2401V87404E-RF Tester:Kungfumaster Liang
Date: 28.AUG.2024 11:10:16