




n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK RB50@0 9.218MHz

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM 64
QAM RB50@0 9.209MHz


n66_10MHz_15kHz_1745MHz_CP-OFDM
QPSK RB52@0 9.281MHz




n66_10MHz_15kHz_1745MHz_CP-OFDM 16
QAM_RB52@0 9.294MHz




n66_10MHz_15kHz_1745MHz_CP-OFDM 64
QAM_RB52@0 9.325MHz




n66_10MHz_15kHz_1745MHz_CP-OFDM 256
QAM_RB52@0 9.283MHz




n66_10MHz_15kHz_1775MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 9.201MHz




n66_10MHz_15kHz_1775MHz_DFT-s-OFDM 16
QPSK_RB50@0 9.205MHz




n66_10MHz_15kHz_1775MHz_DFT-s-OFDM 64
QAM_RB50@0 9.259MHz




n66_10MHz_15kHz_1775MHz_DFT-s-OFDM 64
QAM_RB50@0 9.216MHz




n66_10MHz_15kHz_1775MHz_DFT-s-OFDM 256
QAM_RB50@0 9.210MHz




n66_10MHz_15kHz_1775MHz_CP-OFDM
QPSK_RB52@0 9.281MHz




n66_10MHz_15kHz_1775MHz_CP-OFDM 16
QAM_RB52@0 9.292MHz




n66_10MHz_15kHz_1775MHz_CP-OFDM 64
QAM_RB52@0 9.283MHz




n66_10MHz_15kHz_1775MHz_CP-OFDM 256
QAM_RB52@0 9.291MHz




n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 13.948MHz




n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB75@0 13.941MHz



n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM 16
QAM_RB75@0 14.115MHz



n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM 64
QAM_RB75@0 13.934MHz





n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM 256
QAM_RB75@0 13.927MHz




n66_15MHz_15kHz_1717.5MHz_CP-OFDM
QPSK_RB79@0 14.107MHz




n66_15MHz_15kHz_1717.5MHz_CP-OFDM 64
QAM RB79@0 14.061MHz

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM $\pi/2$
BPSK RB75@0 13.996MHz


n66_15MHz_15kHz_1745MHz_DFT-s-OFDM 16
QAM RB75@0 14.166MHz



n66_15MHz_15kHz_1745MHz_DFT-s-OFDM 256
QAM RB75@0 14.002MHz



n66_15MHz_15kHz_1745MHz_CP-OFDM 16
QAM RB79@0 14.114MHz

n66_15MHz_15kHz_1745MHz_CP-OFDM 256
QAM RB79@0 14.124MHz