




n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.446MHz




n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB36@0 13.441MHz



n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB36@0 13.500MHz




n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB36@0 13.467MHz




n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB36@0 13.445MHz




n77_3_15MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB38@0 13.567MHz




n77_3_15MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB38@0 13.580MHz




n77_3_15MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB38@0 13.575MHz




n77_3_15MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB38@0 13.526MHz




n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.406MHz




n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB36@0 13.454MHz




n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM 16
QAM_RB36@0 13.521MHz




n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.447MHz




n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.463MHz




n77_3_15MHz_30kHz_3972.5MHz_CP-OFDM
QPSK_RB38@0 13.574MHz




n77_3_15MHz_30kHz_3972.5MHz_CP-OFDM 16
QAM_RB38@0 13.565MHz




n77_3_15MHz_30kHz_3972.5MHz_CP-OFDM 64
QAM_RB38@0 13.574MHz




n77_3_15MHz_30kHz_3972.5MHz_CP-OFDM 256
QAM_RB38@0 13.565MHz




n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.090MHz




n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 18.085MHz



n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM 16
QAM_RB50@0 18.098MHz




n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM 64
QAM_RB50@0 18.026MHz




n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM 256
QAM_RB50@0 18.018MHz




n77_3_20MHz_30kHz_3710MHz_CP-OFDM
QPSK_RB51@0 18.170MHz




n77_3_20MHz_30kHz_3710MHz_CP-OFDM 16
QAM_RB51@0 18.172MHz




n77_3_20MHz_30kHz_3710MHz_CP-OFDM 64
QAM_RB51@0 18.182MHz




n77_3_20MHz_30kHz_3710MHz_CP-OFDM 256
QAM_RB51@0 18.184MHz




n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.028MHz




n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB50@0 18.095MHz




n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB50@0 18.081MHz




n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB50@0 18.082MHz




n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB50@0 18.014MHz




n77_3_20MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB51@0 18.170MHz



n77_3_20MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB51@0 18.186MHz



n77_3_20MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB51@0 18.175MHz



n77_3_20MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB51@0 18.193MHz

