



n77_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.459MHz




n77_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.460MHz



n77_2_15MHz_30kHz_3557.5MHz_CP-OFDM
QPSK_RB38@0 13.571MHz



n77_2_15MHz_30kHz_3557.5MHz_CP-OFDM 16
QAM_RB38@0 13.572MHz




n77_2_15MHz_30kHz_3557.5MHz_CP-OFDM 64
QAM_RB38@0 13.578MHz




n77_2_15MHz_30kHz_3557.5MHz_CP-OFDM 256
QAM_RB38@0 13.525MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.465MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 13.446MHz



n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB36@0 13.518MHz



n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB36@0 13.449MHz




n77_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB36@0 13.465MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB38@0 13.565MHz



n77_2_15MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB38@0 13.574MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB38@0 13.574MHz




n77_2_15MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB38@0 13.526MHz




n77_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.451MHz




n77_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 13.451MHz



n77_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM 16
QAM_RB36@0 13.466MHz




n77_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.409MHz




n77_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.462MHz



n77_2_15MHz_30kHz_3692.5MHz_CP-OFDM
QPSK_RB38@0 13.576MHz



n77_2_15MHz_30kHz_3692.5MHz_CP-OFDM 16
QAM_RB38@0 13.526MHz




n77_2_15MHz_30kHz_3692.5MHz_CP-OFDM 64
QAM_RB38@0 13.580MHz




n77_2_15MHz_30kHz_3692.5MHz_CP-OFDM 256
QAM_RB38@0 13.562MHz




n77_2_20MHz_30kHz_3560MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.085MHz




n77_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB50@0 18.086MHz



n77_2_20MHz_30kHz_3560MHz_DFT-s-OFDM 16
QAM_RB50@0 18.025MHz




n77_2_20MHz_30kHz_3560MHz_DFT-s-OFDM 64
QAM_RB50@0 18.082MHz



n77_2_20MHz_30kHz_3560MHz_DFT-s-OFDM 256
QAM_RB50@0 18.028MHz




n77_2_20MHz_30kHz_3560MHz_CP-OFDM
QPSK_RB51@0 18.176MHz



n77_2_20MHz_30kHz_3560MHz_CP-OFDM 16
QAM_RB51@0 18.169MHz




n77_2_20MHz_30kHz_3560MHz_CP-OFDM 64
QAM_RB51@0 18.188MHz



n77_2_20MHz_30kHz_3560MHz_CP-OFDM 256
QAM_RB51@0 18.195MHz



n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.033MHz



n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 18.088MHz



n77_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB50@0 18.026MHz

