






n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM RB24@0 8.566MHz

n78_3_10MHz_30kHz_3750MHz_CP-OFDM 16
OAM RB24@0.8574MHzn78_3_10MHz_30kHz_3750MHz_CP-OFDM 256
OAM RB24@0 8.612MHz


n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK RB24@0 8.573MHz




n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM 64
QAM RB24@0 8.537MHz




n78_3_10MHz_30kHz_3795MHz_CP-OFDM
QPSK RB24@0 8.602MHz




n78_3_10MHz_30kHz_3795MHz_CP-OFDM 64
QAM RB24@0 8.575MHz




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM $\pi/2$
BPSK RB36@0 13.451MHz




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM 16
QAM RB36@0 13.470MHz




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.502MHz




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.464MHz



n78_3_15MHz_30kHz_3707.5MHz_CP-OFDM
QPSK_RB38@0 13.567MHz




n78_3_15MHz_30kHz_3707.5MHz_CP-OFDM 16
QAM_RB38@0 13.561MHz




n78_3_15MHz_30kHz_3707.5MHz_CP-OFDM 64
QAM_RB38@0 13.565MHz




n78_3_15MHz_30kHz_3707.5MHz_CP-OFDM 256
QAM_RB38@0 13.527MHz




n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.461MHz




n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB36@0 13.447MHz



n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB36@0 13.469MHz



n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB36@0 13.506MHz




n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB36@0 13.456MHz




n78_3_15MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB38@0 13.571MHz



n78_3_15MHz_30kHz_3750MHz_CP-OFDM 64
QAM RB38@0 13.578MHz



n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM $\pi/2$
BPSK RB36@0 13.441MHz

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM 16
QAM RB36@0 13.523MHz