



n78_2_90MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB245@0 87.239MHz




n78_2_90MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB245@0 87.207MHz



n78_2_90MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB245@0 87.243MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0 96.497MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 96.189MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB270@0 96.144MHz



n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB270@0 96.145MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB270@0 96.123MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB273@0 97.307MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB273@0 97MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB273@0 97.257MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB273@0 97.373MHz

