



5MHz_High_QPSK_1@24




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:08:44

5MHz_High_QPSK_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:24:17

5MHz_High_16QAM_1@24




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:09:57

5MHz_High_16QAM_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:09:20

10MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:17:27

10MHz_Low_QPSK_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:26:49

10MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:18:37

10MHz_Low_16QAM_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:18:02

10MHz_High_QPSK_1@49




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:29:07

10MHz_High_QPSK_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:28:25

10MHz_High_16QAM_1@49




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:30:31

10MHz_High_16QAM_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 19:29:48

15MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:36:50

15MHz_Low_QPSK_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:36:04

15MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:38:01

15MHz_Low_16QAM_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:37:26

15MHz_High_QPSK_1@74




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:44:04

15MHz_High_QPSK_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:43:20


15MHz_High_16QAM_1@74




15MHz_High_16QAM_75@0




20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0



20MHz_Low_16QAM_100@0




20MHz_High_QPSK_1@99




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:52:42

20MHz_High_QPSK_100@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:51:56

20MHz_High_16QAM_1@99



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:54:14


20MHz_High_16QAM_100@0



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:53:28


B41_2, Normal

2_5MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:56:39

2_5MHz_Low_QPSK_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:56:03

2_5MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:57:49

2_5MHz_Low_16QAM_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:57:14

2_5MHz_High_QPSK_1@24




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:59:40

2_5MHz_High_QPSK_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 19:59:04

2_5MHz_High_16QAM_1@24




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:00:51

2_5MHz_High_16QAM_25@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:00:15

2_10MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:10:49

2_10MHz_Low_QPSK_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:10:12

2_10MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:12:03

2_10MHz_Low_16QAM_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:11:26

2_10MHz_High_QPSK_1@49




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:13:53

2_10MHz_High_QPSK_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:13:14

2_10MHz_High_16QAM_1@49




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:15:10

2_10MHz_High_16QAM_50@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:14:31

2_15MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:19:14

2_15MHz_Low_QPSK_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:18:36

2_15MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:20:28

2_15MHz_Low_16QAM_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 20.JUN.2024 20:19:51

2_15MHz_High_QPSK_1@74




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:23:20

2_15MHz_High_QPSK_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:22:42

2_15MHz_High_16QAM_1@74




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:24:35

2_15MHz_High_16QAM_75@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:23:57

2_20MHz_Low_QPSK_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:28:19

2_20MHz_Low_QPSK_100@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:27:42

2_20MHz_Low_16QAM_1@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:29:34

2_20MHz_Low_16QAM_100@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:28:56

2_20MHz_High_QPSK_1@99




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:49:34

2_20MHz_High_QPSK_100@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:41:47

2_20MHz_High_16QAM_1@99



ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 21:04:42

2_20MHz_High_16QAM_100@0




ProjectNo.:2402U81179E-RF Tester:Karl Liang
 Date: 20.JUN.2024 20:57:08

Spurious Emissions at Antenna Terminal


FCC Part 22H

B5, Normal


1.4MHz_Low_QPSK_1@0 -25.44dBm




1.4MHz_Low_QPSK_6@0 -25.49dBm




1.4MHz_Middle_QPSK_1@0 -24.70dBm



1.4MHz_Middle_QPSK_6@0 -25.96dBm




1.4MHz_High_QPSK_1@0 -25.06dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19 JUN 2024 00:23:13

1.4MHz_High_QPSK_6@0 -24.47dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19 JUN 2024 00:23:27


3MHz_Low_QPSK_1@0 -25.45dBm




3MHz_Low_QPSK_15@0 -25.74dBm




3MHz_Middle_QPSK_1@0 -25.73dBm




3MHz_Middle_QPSK_15@0 -25.17dBm




3MHz_High_QPSK_1@0 -25.31dBm



3MHz_High_QPSK_15@0 -25.88dBm




5MHz_Low_QPSK_1@0 -25.47dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:27:48

5MHz_Low_QPSK_25@0 -25.80dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:28:02

5MHz_Middle_QPSK_1@0 -24.89dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:28:17

5MHz_Middle_QPSK_25@0 -25.51dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:28:31

5MHz_High_QPSK_1@0 -25.22dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:28:46

5MHz_High_QPSK_25@0 -25.27dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:29:01

10MHz_Low_QPSK_1@0 -25.72dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:30:05

10MHz_Low_QPSK_50@0 -25.71dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:30:21

10MHz_Middle_QPSK_1@0 -25.49dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:30:36

10MHz_Middle_QPSK_50@0 -25.03dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:30:52

10MHz_High_QPSK_1@0 -25.74dBm



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:31:08

10MHz_High_QPSK_50@0 -25.76dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:31:24


FCC Part 27

B7, Normal


5MHz_Low_QPSK_1@0 -34.83dBm




5MHz_Low_QPSK_25@0 -34.59dBm




5MHz_Middle_QPSK_1@0 -34.33dBm



5MHz_Middle_QPSK_25@0 -34.70dBm




5MHz_High_QPSK_1@0 -34.33dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:33:49

5MHz_High_QPSK_25@0 -34.80dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:34:10

10MHz_Low_QPSK_1@0 -35.11dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:36:04

10MHz_Low_QPSK_50@0 -34.35dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:36:25

10MHz_Middle_QPSK_1@0 -34.10dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:36:45

10MHz_Middle_QPSK_50@0 -34.68dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:37:06

10MHz_High_QPSK_1@0 -34.84dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:37:27

10MHz_High_QPSK_50@0 -34.60dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:37:47

15MHz_Low_QPSK_1@0 -34.76dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:38:54

15MHz_Low_QPSK_75@0 -34.74dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:39:15

15MHz_Middle_QPSK_1@0 -34.30dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:39:36

15MHz_Middle_QPSK_75@0 -33.46dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:39:56

15MHz_High_QPSK_1@0 -34.65dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:40:16

15MHz_High_QPSK_75@0 -35.15dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:40:36

20MHz_Low_QPSK_1@0 -34.79dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:41:33

20MHz_Low_QPSK_100@0 -34.72dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:41:53

20MHz_Middle_QPSK_1@0 -34.73dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:42:14

20MHz_Middle_QPSK_100@0 -34.43dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:42:34

20MHz_High_QPSK_1@0 -34.63dBm



ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:42:55


20MHz_High_QPSK_100@0 -33.80dBm




ProjectNo.:2402U81179E-RF Tester:Karl Liang
Date: 19.JUN.2024 00:43:15

B38 , Normal


5MHz_Low_QPSK_1@0 -34.67dBm




5MHz_Low_QPSK_25@0 -34.58dBm




5MHz_Middle_QPSK_1@0 -34.56dBm



5MHz_Middle_QPSK_25@0 -34.98dBm



5MHz_High_QPSK_1@0 -34.77dBm



5MHz_High_QPSK_25@0 -33.89dBm

