



LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~25.025GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~15GHz)



5MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:15:05

5MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:15:15

5MHz_High_QPSK_1@0(15GHz~25.675GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:15:24

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:16:14

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:16:24

10MHz_Low_QPSK_1@0(15GHz~25.05GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:16:33

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:16:41

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:16:51

10MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:17:00

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:17:08

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:17:18

10MHz_High_QPSK_1@0(15GHz~25.65GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:17:27

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:18:10

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:18:20

15MHz_Low_QPSK_1@0(15GHz~25.075GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:18:29

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:18:42

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:18:52

15MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:19:01

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:19:13

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:19:23

15MHz_High_QPSK_1@0(15GHz~25.625GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:19:33

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:20:15

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:20:25

20MHz_Low_QPSK_1@0(15GHz~25.1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 13:48:34

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:20:47

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:20:57

20MHz_Middle_QPSK_1@0(15GHz~25.35GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:21:06

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:21:21

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:21:31

20MHz_High_QPSK_1@0(15GHz~25.6GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 08:21:39


LTE Band 12, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



3MHz_High_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:47:58

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:48:15

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:48:33

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:49:15

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:49:35

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:49:55


LTE Band 13, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




5MHz_Low_QPSK_1@0(763MHz~775MHz)




5MHz_Low_QPSK_1@0(793MHz~806MHz)




5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




5MHz_High_QPSK_1@0(30MHz~8.87GHz)



5MHz_High_QPSK_1@0(763MHz~775MHz)




5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 19:53:12

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 15.AUG.2026 13:52:58

10MHz_Middle_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 00:55:10

10MHz_Middle_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 19:54:31

10MHz_Middle_QPSK_1@0(793MHz~806MHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 19:54:37

10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 14.AUG.2026 19:59:02


LTE Band 17, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~8.16GHz)




LTE Band 38, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~25.725GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~15GHz)



5MHz_Middle_QPSK_1@0(15GHz~25.95GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:17:47

5MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:39:29

5MHz_High_QPSK_1@0(15GHz~26.175GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:50:26

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:39:52

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:40:27

10MHz_Low_QPSK_1@0(15GHz~25.75GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:11:23

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:40:02

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:41:05

10MHz_Middle_QPSK_1@0(15GHz~25.95GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:11:58

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:40:13

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:41:43

10MHz_High_QPSK_1@0(15GHz~26.15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:12:11

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:40:50

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:43:00

15MHz_Low_QPSK_1@0(15GHz~25.775GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:12:50

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:41:01

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:43:33

15MHz_Middle_QPSK_1@0(15GHz~25.95GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:13:03

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:41:14

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 30.JUL.2026 23:44:08

15MHz_High_QPSK_1@0(15GHz~26.125GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:13:16

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:13:52

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:14:01

20MHz_Low_QPSK_1@0(15GHz~25.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:14:10

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:14:33

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:14:44

20MHz_Middle_QPSK_1@0(15GHz~25.95GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:14:53

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:15:04

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:15:14

20MHz_High_QPSK_1@0(15GHz~26.1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:15:24


LTE Band 41, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~1GHz)




5MHz_Low_QPSK_1@0(1GHz~15GHz)




5MHz_Low_QPSK_1@0(15GHz~24.985GHz)




5MHz_Middle_QPSK_1@0(30MHz~1GHz)




5MHz_Middle_QPSK_1@0(1GHz~15GHz)



5MHz_Middle_QPSK_1@0(15GHz~25.93GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:42:53

5MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:43:03

5MHz_High_QPSK_1@0(15GHz~26.875GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:51:04

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:51:38

10MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:51:48

10MHz_Low_QPSK_1@0(15GHz~25.01GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:51:57

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:06

10MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:16

10MHz_Middle_QPSK_1@0(15GHz~25.93GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:25

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:38

10MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:48

10MHz_High_QPSK_1@0(15GHz~26.85GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:52:57

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:53:45

15MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:53:55

15MHz_Low_QPSK_1@0(15GHz~25.035GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:54:04

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:54:21

15MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:54:30

15MHz_Middle_QPSK_1@0(15GHz~25.93GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:54:40

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:54:53

15MHz_High_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:55:03

15MHz_High_QPSK_1@0(15GHz~26.825GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:55:12

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:55:52

20MHz_Low_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:02

20MHz_Low_QPSK_1@0(15GHz~25.06GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:11

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:21

20MHz_Middle_QPSK_1@0(1GHz~15GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:30

20MHz_Middle_QPSK_1@0(15GHz~25.93GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:40

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:50

20MHz_High_QPSK_1@0(1GHz~15GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:56:59

20MHz_High_QPSK_1@0(15GHz~26.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 00:57:09


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:25:43

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:25:56

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:26:08

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:26:49

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:27:01

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:27:14

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:28:10

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:28:22

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:28:34

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:29:13

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:29:25

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2602V33182E-RF Tester:Loge Long
Date: 31.JUL.2026 14:29:38

***** END *****