



B7 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:06:53

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:07:29

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:08:05

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:08:46

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:09:21

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:10:01

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:10:40

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:11:16

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:11:51

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:12:31

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:13:07


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:13:43


B12 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:04:42

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:05:41

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:06:41

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:07:44

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:08:49

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:09:48

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:10:51

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:11:50

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:12:50

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:13:53

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:14:54


10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:15:53


B17 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:17:14

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:18:15

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:19:24

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:20:28

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:21:29


10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:22:30


B38 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:14:49

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:15:25

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:16:01

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:16:42

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:17:19

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Testers:Chin Qin
Date: 7.MAR.2025 00:17:55

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:18:37

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:19:13

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:19:49

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:20:39

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:21:16


20MHz_High_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 7.MAR.2025 00:21:53


B66 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:23:57

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:25:00

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:26:03

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:27:10

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:28:13

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:29:24

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:30:32

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:31:36

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:32:38

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:33:44

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:34:49

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:35:53

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:37:01

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:38:05

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:39:16

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:40:22

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:41:26


20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 6.MAR.2025 18:42:29


B41_2 , Normal
1RB was the worst case

2_5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:38:43

2_5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:39:31

2_5MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:40:19

2_10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:41:46

2_10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:42:34

2_10MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:43:22

2_15MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:44:50

2_15MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:45:38

2_15MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:46:25

2_20MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:47:53

2_20MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:48:41

2_20MHz_High_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2503Q32696E-RF Tester:Chin Qin
Date: 17.MAR.2025 08:49:29

***** END *****