



15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:45:05

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:45:40

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:46:14

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:47:39

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:48:14

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 1.SEP.2025 17:48:49


FCC Part 90**LTE Band 14, Normal**

Mode	Value (dBm)	Limit	Verdict
5MHz_Low_QPSK_1@0(30MHz~8.98GHz)	-33.98	See Graphs	Pass
5MHz_Low_QPSK_1@0(1559MHz~1610MHz)	-47.60	See Graphs	Pass
5MHz_Middle_QPSK_1@0(30MHz~8.98GHz)	-34.25	See Graphs	Pass
5MHz_Middle_QPSK_1@0(1559MHz~1610MHz)	-47.60	See Graphs	Pass
5MHz_High_QPSK_1@0(30MHz~8.98GHz)	-33.95	See Graphs	Pass
5MHz_High_QPSK_1@0(1559MHz~1610MHz)	-47.18	See Graphs	Pass
10MHz_Middle_QPSK_1@0(30MHz~8.98GHz)	-34.02	See Graphs	Pass
10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)	-47.60	See Graphs	Pass


Note:1RB was the worst case.

LTE Band 14, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.98GHz)




5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




5MHz_Middle_QPSK_1@0(30MHz~8.98GHz)




5MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




5MHz_High_QPSK_1@0(30MHz~8.98GHz)



5MHz_High_QPSK_1@0(1559MHz~1610MHz)




10MHz_Middle_QPSK_1@0(30MHz~8.98GHz)



ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 2.SEP.2025 09:59:02

10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)



ProjectNo.:2507W20891E-RF Tester:Braylon Ma
Date: 2.SEP.2025 10:16:44