


FCC Part 27


Band 4 , Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:49:38

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:49:57

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:50:15

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:03:56

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:04:38

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:05:19

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:07:18

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:07:59

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:08:40

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:10:48

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:11:29


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:12:10


Band 7, Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:32:10

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:32:29

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:32:49

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:35:04

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:35:49

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:36:32

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:37:39

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:38:22

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:39:07

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:41:07

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:41:49


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 14:42:30


Band 66 , Normal
 1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:43:26

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:43:44

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:44:01

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:44:59

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:45:18

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Teeter:Loge Long
 Date: 12.FEB.2025 14:45:37

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:46:00

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:46:21

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:46:42

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:47:05

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:47:47

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:48:27

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:49:56

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:50:37

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:51:16

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:51:56

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:52:32

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:53:09

**** END ****