



Band 7, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:49:18

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:50:29

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:51:41

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:54:29

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:56:46

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:59:03

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:02:18

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:04:37

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:06:59

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:10:20

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:12:40


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 17:15:01


Band 66, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:13:19

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:14:23

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:15:28

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:16:38

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:17:43

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:18:49

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:20:29

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:21:39

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:22:45

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:23:52

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:26:01

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W13811E-RF Tester:Braylon Ma
Date: 31.OCT.2025 16:28:10

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:30:46

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:32:56

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:35:09

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:38:48

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:40:56

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507W13811E-RF Tester: Baylon Ma
Date: 31.OCT.2025 16:43:05