



5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:17:11

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:17:51

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:18:32

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:20:21

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:21:46

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:23:11

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:25:38

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:27:01

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:28:26

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:31:02

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:32:26


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 14:33:49


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:15:04

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:15:49

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:16:35

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:17:49

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:19:19

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Testers:Baylon Ma
Date: 7_JUN.2026 15:20:49

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:22:49

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:24:21

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:25:57

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:27:57

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:29:30


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507A33259E-RF Tester: Braylon Ma
Date: 7..JPN.2026 15:31:02


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:49:04

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:49:44

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:50:24

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:51:08

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:51:49

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testert:Braydon Ma
Date: 7_JUN.2026 14:52:29

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:53:12

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:53:52

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:54:33

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:55:17

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:56:40

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Testset: Braylon Ma
Date: 7..JPN.2026 14:58:02

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 14:59:27

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 15:00:49

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 15:02:10

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 15:04:47

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 15:06:12

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507A33259E-RF Tester: Breydon Ma
Date: 7 JUN 2026 15:07:34