



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:05:10

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:06:30

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:07:55

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:09:48

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:11:12


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:12:41


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:32:25

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:33:28

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:34:32

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:37:27

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:39:42

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Testert:Baylon Ma
Date: 15.DEC.2025 17:42:07

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 17:47:11

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 17:49:30

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 17:51:52

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 17:55:41

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 17:57:59


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 15.DEC.2025 18:00:22


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:26:34

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:27:15

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:27:54

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:28:48

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:29:27

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Testers:Braylon Ma
Date: 12.DEC.2025 10:30:07

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:31:00

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:31:40

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:32:19

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:33:09

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:34:29

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Braylon Ma
Date: 12.DEC.2025 10:35:48

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:38:14

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:39:34

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:40:53

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:42:16

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:43:36

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Z24683E-RF Tester: Breydon Ma
Date: 12.DEC.2025 10:44:56