



5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:08:43

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:09:03

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:09:24

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:09:47

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:10:08

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:10:29

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:10:53

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:11:13

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:11:33

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:11:57

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:12:18

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2602S35570E-RF Tester:Permin Fu
Date: 25.APR.2026 02:12:38


LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 10:31:23

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 10:35:11

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 09:41:58

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 09:44:45

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 10:20:56

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2602S35570E-RF Tester:Fermin Fu
Date: 28.APR.2026 09:48:19


LTE Band 38, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




5MHz_High_QPSK_1@0(30MHz~27.2GHz)




10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



10MHz_High_QPSK_1@0(30MHz~27.2GHz)




15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 28.APR.2026 10:22:38

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 26.APR.2026 16:50:16

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 26.APR.2026 16:13:23

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 28.APR.2026 10:24:57

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 28.APR.2026 10:02:13

20MHz_High_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2602S35570E-RF Tester:Feimin Fu
Date: 28.APR.2026 10:03:34

***** END *****