

October 4, 2023

RE: Justification for label location regarding application for certification

FCC ID: 2BAFL-GC848354


IC Number: 30137-GC848354

To whom it may concern:

This letter is to justify the choice of label location for the device bearing the above FCC ID and IC Number. Due to limited space available to the placement of the label and to ensure it remains viewable when the device is attached to a host circuit board, the location was chosen to be on the RF shield cover. The RF shield frame is permanently affixed to the device (soldered) and the RF shield cover snaps onto the frame with twelve detents on the sides of the cover mated to holes in the frame. While this attachment is not permanent, the RF shield is attached in factory, is not intended to be removed, and further is very difficult to remove if attempted.

Please contact the undersigned if you have any questions or need any further information.

Regards,

A handwritten signature in black ink, appearing to read 'Michael Lockerbie', with a stylized flourish at the end.

Michael Lockerbie
Co-founder