



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:37:01

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:38:21

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:39:41

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:41:05

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:42:32


20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 11:43:53

Band 7, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:24:00

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:25:23

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:26:46

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:28:12

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:29:38


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74133E-RF Tester: Breydon Ma
Date: 22_JUG, 2025 14:31:11

Band 66, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:50:24

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:51:08

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:51:51

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:52:37

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:54:05

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:55:32

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:57:02

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 13:58:37

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 14:00:05

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 14:04:02

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 14:05:32

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2507W74133E-RF Tester:Braylon Ma
Date: 22.AUG.2025 14:07:02