



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:01:14

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:02:42

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:04:05

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:39:14

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:10:05


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 14:11:31


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:41:15

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:41:55

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:42:35

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:43:17

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:44:37

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Testers:Baylon Ma
Date: 9,SEP,2025 14:45:59

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:47:23

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:48:44

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:50:06

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:51:32

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:52:55


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507W74132E-RF Tester: Breydon Ma
Date: 9, SEP, 2025 14:54:19


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 14:59:49

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 15:00:37

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 15:01:24

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 15:02:13

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 15:03:06

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Testers:Braylon Ma
Date: 9.SEP.2025 15:03:53

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:04:44

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:05:32

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:06:18

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:07:06

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:08:43

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:10:21

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:11:59

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:13:37

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:15:13

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:16:52

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:18:32

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2507W74132E-RF Tester:Braylon Ma
Date: 9.SEP.2025 15:20:16