



Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:06:38

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:08:59

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:10:10

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:12:04

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:14:20

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28_JUN.2026 13:16:37

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:19:59

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:22:19

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:24:38

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:28:11

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:30:29


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 13:32:50

Band 66, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 11:59:02

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 12:00:04

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 12:01:08

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 12:03:00

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 12:05:17

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Braylon Ma
Date: 28 JUN 2026 12:07:29

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:09:58

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:12:09

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:14:20

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:16:32

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:18:43

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607P37970E-RF Tester: Baylon Ma
Date: 28.JUN.2026 12:20:53