




15MHz_High_16QAM_25@50




20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




20MHz_Low_16QAM_25@0



20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 13.JAN.2025 15:20:47


20MHz_High_16QAM_1@99



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 13.JAN.2025 15:21:26


Band 66 , Normal

20MHz_High_16QAM_25@75




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 14.JAN.2025 16:34:45

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 13.JAN.2025 09:34:10

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 13.JAN.2025 09:34:34

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 13.JAN.2025 09:34:57


1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




1.4MHz_High_16QAM_6@0




3MHz_Low_QPSK_1@0




3MHz_Low_QPSK_15@0




3MHz_Low_16QAM_1@0




3MHz_Low_16QAM_15@0




3MHz_High_QPSK_1@14




3MHz_High_QPSK_15@0




3MHz_High_16QAM_1@14




3MHz_High_16QAM_15@0




5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




5MHz_High_16QAM_25@0




10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_25@0




10MHz_High_QPSK_1@49




10MHz_High_QPSK_50@0




10MHz_High_16QAM_1@49



10MHz_High_16QAM_25@25





15MHz_Low_QPSK_1@0





15MHz_Low_QPSK_75@0

15MHz_Low_16QAM_1@0





15MHz_Low_16QAM_25@0

15MHz_High_QPSK_1@74




15MHz_High_QPSK_75@0


15MHz_High_16QAM_1@74




15MHz_High_16QAM_25@50




20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




20MHz_Low_16QAM_25@0




20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99



20MHz_High_16QAM_25@75




Spurious Emissions at Antenna Terminal

FCC Part 22H


Band 5 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:09:24

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:10:38

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:11:53

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:13:28

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:14:41

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 17:15:56


5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



10MHz_High_QPSK_1@0(30MHz~9.49GHz)




FCC Part 24E

Band 2 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:47:22

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:47:41

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:20:55

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:48:03

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:23:05

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:23:43

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:49:31

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:49:50

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:50:09

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:51:53

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:52:34

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 19:53:14


15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~20.1GHz)



20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




20MHz_High_QPSK_1@0(30MHz~20.1GHz)



FCC Part 27


Band 4 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 20:02:24

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 20:02:43

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 11.JAN.2025 20:03:02

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:36:40

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:37:56

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:39:14

5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:40:47

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:42:03

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:43:18

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:45:00

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:47:31

10MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2402A65054E-RF Tester:Loge Long
Date: 12.JAN.2025 16:50:05