



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:17:53

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:19:22

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:20:49

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:22:43

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:24:09


20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:25:43

Band 7, Normal**1RB was the worst case**


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)

ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:51:39


5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)

ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:52:21


5MHz_High_QPSK_1@0(30MHz~26.7GHz)

ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:53:04


10MHz_Low_QPSK_1@0(30MHz~26.7GHz)

ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:55:04


10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)

ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:56:34

10MHz_High_QPSK_1@0(30MHz~26.7GHz)


ProjectNo.: 2507Z18185E-RF Testers:Baylon Ma
Date: 19.NOV.2025 04:58:07

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:01:11

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:02:48

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:04:22

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:06:40

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:08:14


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 05:09:50


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:39:01

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:39:44

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:40:28

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:41:14

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:41:58

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Testert:Braylon Ma
Date: 19.NOV.2025 06:42:42

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:43:28

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:44:11

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:44:54

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:46:19

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:47:48

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Braylon Ma
Date: 19.NOV.2025 06:49:15

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:50:48

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:52:18

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:53:45

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:55:58

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:57:24

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507Z18185E-RF Tester: Breydon Ma
Date: 19.NOV.2025 06:58:52