



5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:25:30

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:26:11

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:26:52

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:28:42

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:30:07

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:31:29

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:33:59

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:35:23

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:36:46

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:38:13

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:39:37


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:41:00


Band 7, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:34:50

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:35:32

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:36:14

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:36:58

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:38:23

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:39:53

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:41:28

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:43:08

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:44:42

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:46:17

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:47:50


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 21:49:23


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:54:37

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:55:18

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:56:00

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:56:43

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:57:23

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:58:04

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:58:47

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 22:59:31

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 23:00:14

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 23:01:42

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 23:03:08

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester: Braylon Ma
Date: 10.NOV.2025 23:04:32

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:05:58

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:07:22

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:08:44

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:10:49

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:12:13

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2507V18169E-RF Tester:Braydon Ma
Date: 10.NOV.2025 23:13:36