



Band 38, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:03:42

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:04:23

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:05:05

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:06:49

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:08:14

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Testers: Breydon Ma
Date: 30-JUN-2026 14:09:42

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:12:21

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:13:52

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:15:23

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:18:40

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:20:13


20MHz_High_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-JUN-2026 14:21:47


Band 41, Normal**1RB was the worst case**

5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:23:42

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:24:28

5MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:25:15

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:27:07

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:28:38

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.: 2607S05196E-RF Testers:Baylon Ma
Date: 30-JUN-2026 14:30:09

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:32:46

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:34:19

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:35:50

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:38:28

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:40:00


20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2607S05196E-RF Tester:Braylon Ma
Date: 30-July,2026 14:41:32


Band 66, Normal**1RB was the worst case**

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:36:29

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:37:10

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:37:51

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:38:34

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:39:14

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Testers:Benyoun Ma
Date: 30-JUN-2026 13:39:56

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:40:39

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:41:20

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:42:00

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:42:43

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:44:05

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Braylon Ma
Date: 30-July-2026 13:45:26

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:47:33

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:48:56

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:50:21

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:51:48

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:53:09

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.: 2607S05196E-RF Tester: Bawlyon Ma
Date: 30-JUN-2026 13:54:30