

Product Equality Declaration

We, Samsung Electronics Co., Ltd., declare on our sole responsibility that the products

SGH-S300, SGH-S308

are identical to the measured products on Report no. *303FCC24/2002 (EMC)* and Report No. *0674-01-01b/02 (SAR)*. in all relevant part. All devices have identical hardware configuration.

SGH-S300 is granted at FCC ID: *A3LSGHS300*.

The *SGH-S308* for granting at FCC is *A3LSGHS308*

The only difference between the *SGH-S308* and the *SGH-S300* is:

- *Change UI for Chinese.*

Company name: Samsung Electronics Co., Ltd.

Address: #94-1, Imsoo-dong, Gumi-city, Kyung-Buk, Korea 730-350

Phone: +82 54 479 5794

Email: lbkuk@samsung.com



JONG YONG YUN/Vice Chairman&CEO

Kyung-Buk, Korea / Nov 23 '02

Place and Date

Signature and Company stamp.

	Samsung Electronics Co.Ltd	
DOCUMENT:	Project: SGH-S308	
Date: 13,SEP,2002	Reference: SGH-S300	
Author: W.H.Yoo	Status: Confirmed	Version: S38ZCVI1

MODIFICATIONS DECLARATION

Keywords: (PCS, TTT, Cetecom, Inc.)

Abstract:

This is an application for type approval (TA) of **SGH-S308** mobile station software version **S38ZCVI1**.

REVISION HISTORY

Version	Date	Description	Authors
Rev S1.6H	/ 07/2002	- Final software version of SGH-S300	W.H.Yoo
S38ZCVI1	/ 09/2002	- Protocol Software and hardware is same as SGH-S300. Chinese UI Applied based on SGH- S300 Software (Rev S1.6H)	

Table of Contents

1. GENERAL

- 1.1 Identification of T.A. Object
- 1.2 Method of Documentation

2. DESCRIPTION OF THE CHANGES AND RE-TESTING CONSEQUENCES

- 2.1 Changes
 - 2.1.1 *SW version S38ZCVII*
- 2.2 Summary of Re-testing Consequences
 - 2.2.1 *SW version S38ZCVII*

1. GENERAL

1.1 Identification of TA object

This is an application for type approval (TA) of the **SGH-S308** mobile station software **S38ZCVI1**.

The application is based on the currently undergoing type approval measurement **S1.6H** (final version of SGH-S300). This software is used in a mobile station type: **SGH-S308**

This document:

1. Highlights the differences between;
 - The new software version **S38ZCVI1**.
 - The previous software versions **S1.6H**
2. Recommends applicable TA tests to be re-run to verify changes made.

1.2 Method of documentation

The following steps have been performed to identify the need for re-testing:

1. Identify all source code files that have been changed
2. Select files deemed critical with respect to re-testing.
3. List of all revision steps made in selected files.
4. Trace the change report belonging to each of one of the revision steps.
5. Suggest re-testing based on an analysis of the contents of each change report.

2. DESCRIPTION OF THE CHANGES AND RE-TESTING CONSEQUENCES

2.1 Changes

2.1.1 SW Version <S38ZCVI1>

C.R.	Short Description	Re-testing
1.	<change> The European of SGH-S300 is translated into Chinese_S, Chinese_T, English for China Type and UI applied	None
2.	<change> handling Read and Write function in case of Chinese character	None
3.	<change>make Chinese character display in Wap	None
4.	<change>Character conversion handling for EasyGPRS connection in Chinese	None

2.2 Summary of re-testing consequences