

Interactive Technologies Inc

EXHIBIT A
ID Label / Location

 **S4006**
Household Fire and Burglary
Warning System Control Unit
ISSUE NO: AE6558 05/23/02

Transformer: ITI Part#: 22-109 Power Input: 120 VAC, 125 mA
Canada: 22-109-CN Power Output: 9 VAC, 700 mA

Model: 60-875-95R
60-875-00-3-SPN
60-875-01-3-SPN

GE Interlogix Inc.
2266 North 2nd Street
North St. Paul, MN 55109
1-800-777-1415

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code ANSI/NFPA 72-1993 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02669) INTERNAL BATTERY: 6VDC The battery is automatically tested every 4 hours. REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT ONLY: Yuasa Battery America, Part No.NP1.2-6 Lead Acid or Topin Battery Ltd Part No. TP6-1.3

Wiring Diagram: See installation Manual 486-1873.

This system is intended to be checked by a qualified technician at least every three years.

Complies with Part 68 ACTA Rules
ACTA Reg. No. B4ZUSA-46042-AL-T
Ringer Equivalence 0.1B (AC)
Load Number 0.1

This device complies with FCC rules Part 15. Operation is subject to the following two conditions: 1) this device may not cause harmful interference and (2) this device must accept any interference that maybe received, including interference that may cause undesired operation.

FCC ID: B4Z-787E-SIMON US Patents 4,855,713,
IC: 867A 787SIMON 4,864,636 and others pending

WARNING:
DO NOT CONNECT TO A RECEPTACLE CONTROLLED BY A
SWITCH. HIGH VOLTAGE; DISCONNECT TELCO BEFORE
SERVICING. CAUTION: IMPROPER CONNECTIONS MAY
RESULT IN DAMAGE TO THE EQUIPMENT. 422-1932-04 Rev. D

05/23/02 2:12 PM

FCC ID: B4Z-787E-SIMON

W:\iti2vol2\PRJ\DEG\ACTIVE\60-875-95R Simon 3 Domestic\Approvals-Listings-Technical
File\FCC\Part 15 Submittal\pieces\id_label.DOC