



Block Diagram of UNC





MURATA MFG CO., LTD. KYOTO JAPAN


高压部と低压部の沿面距離は 3mm 以上取ること

FCC ID: BDBF-21002A

UNCS

UNC5

S 400029015S




UNITED STATES DEPARTMENT OF JUSTICE

FCC ID: BDBF21002A


Ok Date Completed: _____
 U: _____
 P2H: _____
 Drawing Number: 40599101SS

CONFIDENTIAL




FCC ID: BDBF21002A

[illegible]



RAM3	4M	15M
RS03	未実装	未実装
RS04	未実装	未実装
RS05	未実装	未実装
RS06	未実装	未実装




FCC ID: BDF21002A	
MEMORY TIME	
Def. Data Comparison	
Part No.	R51
Part Name	40590801SS

[illegible][illegible]

		銀行振込	
		Date Corporation	
Total		R\$1	
Bank name		Paying number	40290801SS
Branch			/
Account			
Currency			

4059080155

OKI CONFIDENTIAL




FCC ID: BDBF21002A


MODEM

Oral Date Composition

705

4053080155






FCC ID: BDBF21002A

D/R: DRY


Title		Date		Author		Reviewer		Status	
RS1		06-06-00		GORDON, R. L.				40550801SS	
Drawing Number		Revision		Date		By		Check	
40550801SS									



FAN/S MOTOR


201

4059080155



OK, DATE CORRECTION
R-1
4059801SS

FCC ID: BDBF2002A




MD(7:0)

MD(7:0)

MA(14:0)

MA(14:0)



FCC ID: BDBF21002A

TITLE	
R51	
40590801SS	
12	

