

October 6,2000

**Federal Communications Commission
Equipment Authorization Division,
Applications Processing Branch
7435 Oakland Mills Road
Columbia, MD 21046**

RE) FCC ID: BRWPYTHON (EA98947)

To whom it may concern;

Please refer to the additional information listed below while reviewing the BRWPYTHON System.

- 1) Section 95.645 (b) states that plug-in crystals must not be accessible to the user. Indicate whether or not crystals are accessible to the user.**

Although the transmitter crystal is visible from the back of the transmitter, each crystal is glued in place prior to shipment making it a permanent installation. Consumer removal of the crystal will normally result in damage to the crystal. Therefore, frequency changes are done at the service center only.

- 2) The Manual must contain warnings per section 95.653**

A) Please refer to the manual attachment for this information

B) All content for operation is contained in the instruction manual.

- 1) All instructions are contained in the instruction manual.
- 2) There are no adjustments accessible to the user that would be in violation with the FCC rules, except as noted in the section #3 below.
- 3) Noted. We will be adding the following information to the instruction manual under "Frequency Chart":

"Note: The Federal Communications Commission (FCC) requires that changes in radio frequency must be performed by an authorized service technician only (Horizon Service Center).

Any frequency changes made by a non-certified technician may result in a violation of the FCC rules"

- 4) This section is not applicable to our use.

If there is any further information required, please contact me directly at:

Horizon Hobby Distributors
ATTN: Len Sabato
Fax: 217-355-0058
Phone: 217-352-1958 Ext. 454
lsabato@horizonhobby.com

Best Regards;
Len Sabato