

Senton GmbH • Äussere Frühlingsstrasse 45 • D-94315 Straubing

Timothy R. Johnson
American TCB

2003-07-09

In reference to FCC ID: CCRST5

- 1) Conducted carrier power measurement has been performed unmodulated.
- 2) The Emission designator in the manual has been corrected.

Senton GmbH



Johann Roidt