



TELEPHONE: (352) 472-5500
(888) 472-2424
FAX: (352) 472-2030
E-MAIL: info@timcoengr.com
WEBSITE: www.timcoengr.com

TIMCO ENGINEERING INC.
25355 West Newberry Road
PO Box 370
Newberry, Florida 32669
sid2s@timcoengr.com

9/30/98

TO: George Tanahill
FCC

Subject: FCCID :H78ATS100

REFERENCE: CORRESPONDANCE ID: 3446

1. ATTACHED YOU WILL FIND A CORRECTED OCCUPIED WITH 100Hz RESOLUTION.
2. 90.217 ATTACHED IS LABELED PLOT. I thought that the Toff was not required for Transmitters under 6.0Watts. Has this requirement changed?
3. IN the the original application the maximum deviation was set in a manner that would allow greater than 2.5KHz deviation at 1.0KHz and I did not understand that the deviation on any frequency could not exceed 2.5KHz. So in the NEW modulation limiting plots I set the maximum deviation to be 2.5KHz and remeasured the modulation limiting.

BEST REGARDS,

Sid Sanders
sid2s@timcoengr.com