



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 28, 2004

RE: FCC ID: H8NWLL4030_ATCB001949
Attention: Ellis Wu

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the operational description in the original grant is extremely minimal and gives no indication of the turbo mode capability. Please verify (show) that the device had the full capability of operating in the turbo mode when it was originally granted and that there has been absolutely no modifications to the unit other than enabling the capability for turbo mode. Please explain why this was not tested in the original application.
2. Please note that the plots on pages 70 to 73 show the receiver is in an UNCAL state. Please explain and please correct as necessary.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.