

Olicom / March 31, 1999

FCC ID: HST217

Exhibit E Manual

The following page shows the FCC statements in our manual.

RAPIDFIRE™ 3150

TOKEN-RING 16/4 PCI ADAPTER



User Guide



olicom
THE NETWORKING COMPANY

Trademarks

GoCard and the Olicom clasped hands logo are registered trademarks of Olicom A/S.

CellDriver, ClearServer, ClearSession, ClearSight, CrossFire, LANscout, PowerMACH and RapidFire are trademarks of Olicom A/S.

ClearCare, ClearPartner, ClearStep and ExpertWatch are service marks of Olicom A/S.

Olicom is a registered trademark.

Other brands and product names are trademarks, registered trademarks, service marks or registered service marks of their respective holders

About this Publication

Olicom A/S reserves the right to modify the information given in this publication without prior notice. The warranty terms and conditions applicable for your purchase of this equipment are given at the time of purchase. Consult your place of purchase for details.

Publication: DOC-7044 v. 1.00.00, P/N: 710001689

© Copyright Olicom A/S, Denmark, January 1999

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of the publisher.

FCC Compliance

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and the receiver.
- Connect the equipment into an outlet on a circuit different from the receiver's.
- Consult the dealer or an experienced radio/television technician for help.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1)

This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Recommended Cable Types

Recommended cable types for the network cabling are Shielded Twisted-Pair (STP) Type 1A and unshielded Twisted-Pair (UTP) Category 5.

Conformance with FCC Class B requires use of shielded cabling which may be either STP or S-UTP.

Modifications

If the device is changed or modified without the express approval of Olicom A/S the user may void his or her authority to operate the equipment.

Declaration of Conformity

We Olicom A/S
Nybrovej 114
DK-2800 Lyngby
Denmark

CLASS 1 LASER PRODUCT

declare under our sole responsibility that the product

Olicom RapidFire 3150 Token-Ring 16/4 PCI Adapter
to which this declaration relates is in conformity with the following standards or other normative documents
EN50082-1
EN55022
EN60950
EN60825-1

following the provisions of 89/336/EEC and 73/23/EEC Directives.