

Phoenix Test Lab

Mr. Brandhorst

Torsten Lohoff
09.05.2006
Phone +49 (0) 2102 749 306
Fax +49 (0) 2102 749 350

Re-testing of Motorola H5, FCC ID IHDT6FB1

Dear Mr. Brandhorst,

we have analyzed the difference between the first hardware version T4 and T6. Full FCC Part 15.247 testing was done on hardware version T4 (see test report 4_MOT_0705_TAS_FCCc). After analyzing the changes in hardware version T6 (see also attachment), we came to the conclusion that re-testing of Peak Power Output and Spurious Radiated Emission shall be done (see test report 4_MOT_0705_TAS_FCCd).

We can also confirm that the changes from FCC rules 2004 to 2005 do not affect the performed test cases.

Best Regards

Torsten Lohoff