



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 29, 2002

RE: Rokonet Electronics Ltd.

FCC ID: JE4KCLP

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide clearer (or higher resolution) close up internal photographs of the top and bottom of each independent board, including the transmitter board and antenna if possible.
- 2) Please provide an exhibit as part of the label information which shows where the label is placed.
- 3) Please provide a higher resolution schematic, as the one provided can not be clearly read.
- 4) The loop antenna was positioned vertically and rotated about its axis. However, the EUT should also be tested with the loop antenna positioned about the horizontal axis. Please provide additional test data or attestations as to the worse case positioning of the loop antenna.
- 5) Please explain why the fundamental field strength in plot A2 is much higher than that reported in plot A1 or the data table.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.