



15 July 2005

Federal Communications Commission
445 Twelfth St., SW
Washington, D.C. 20554

Subject: Reason for Two Assembly Numbers, FCC ID: JHIGNET

This letter is to communicate the reason for reference of two model numbers (248293, 248294) in the User Installation Manual. It is necessary to have separate model numbers for two distinct configurations to provide for different mounting requirements of the host products. The RF design and function of the two models are identical. It is intended that the application cover both configurations.

Regards,

Mark King
Senior Project Engineer
Lubrication Equipment Division

cc: Jim Blaha, L.S. Compliance