



Balboa spa remote FCC ID: MG3URC033

May 7, 2003,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850

RE: FCC ID: MG3URC033

When a remote key that transmits RF at 433.92 MHz is released the RF transmitter is disabled automatically. Any key that transmits RF is disabled typically 3.8 milli seconds before the remote's time base ceramic oscillator (8.0 MHz) stops oscillating. Even if some reason a key that transmits RF is stuck, it transmits RF for 30 seconds and then the remote times out. We refer to this as the stuck key time out. Here again the RF key is disabled 3.8 milli seconds before the ceramic oscillator reaches the 30 seconds time out.

Regards,

Jesse Mendez
Staff Electrical Engineer.

Universal Electronics, Inc.
6101 Gateway Drive, Cypress, CA 90630-4841
Tel: 714 820-1000 FAX: 714-820-1010