



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 10, 2005

RE: FCC ID: MSQJ201_ATCB002837
Attention: Daniel Lee

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that while the SAR report (pdf page 35) states that "The co-location of GSM and BT was also verified for the compliance" there does not appear to be data to back this statement. Please note that the FCC expects to have plotted data of the BT active on the highest SAR level recorded for GSM. This is usually done by finding the highest SAR value and then turning on the BT device to insure that the BT has not caused any significant increase in SAR. Please provide or please point to the data plots where the BT device was transmitting simultaneously with the GSM.
2. FYI – no need to respond at this time. Please note that the table of results for EIRP on page 11 of the test report only provides the final results but does not provide the factors mentioned in the formula. Please note that actual data as well as the final results should be provided. Please provide this in future reports.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.