

Reason for Change:

- Tuned the variable resistor VR4 (100K)

(Customer Request)

Effect on Change:

- Increased the occupied bandwidth.
- Update the TCB certificate due to the change of Emission Designator based on the new measured occupied bandwidth.