


Prüfbericht - Nr.:

Test Report No.

14005577 001

Seite 1 von 4

Page 1 of 4



Remark: The significant narrow band emission at 49.8 MHz was generated by transmitter.


Prüfbericht - Nr.:

14005577 001

Test Report No.

Seite 2 von 4

Page 2 of 4



Remark: The significant narrow band emission at 49.68 MHz was generated by Transmitter.

MES TUV120304B01.PK
LIM FCC P15.109 Class B

9397
49MHz, Rx
Vent.
Motor 0/4


Prüfbericht - Nr.:

Test Report No.

14005577 001

Seite 3 von 4

Page 3 of 4



— MES TUV120304B03.PK
- - - LIM FCC P15.109 Class B

*p3 p7
41415 Rx
Vent.
motor off*

Prüfbericht - Nr.:

14005577 001

Test Report No.


Seite 4 von 4

Page 4 of 4

14005577 001

lucky plastic

9387
C 844, Rx
Horn.
Horn.



MES TUV120304B04.PK
LIM FCC P15.109 Class B