



HERMON LABORATORIES

August 18, 2005

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated August 15, 2005; Telematics Wireless Ltd.
FCC ID:NTAFP300RA, ATCB002645

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The revised file "Circuit_description_16547__rev1" was uploaded on August 18, 2005 via Operational Description folder. Sorry for printing mistake.
- 2) The revised file "Tune_up_procedure_16547_rev1" was uploaded on August 18, 2005.
- 3) Yes, please make the part list and tune up procedure as confidential files – "Confidentiality_letter_16547_rev1" was uploaded on August 18, 2005 via Additional Information folder.
- 4) The User Manual was corrected, "User_manual_16547_rev1" was uploaded on August 18, 2005.
- 5) A mention about RF filters was deleted, please refer to corrected "User_manual_16547_rev1".
- 6) Please refer to last paragraph on page 2 of corrected "User_manual_16547_rev1".
- 7) The corrected "Block_diagram_16547_rev1" was uploaded on August 18, 2005.
- 8) The revised test report with removed section about RF exposure measurement, TELRAD_FCC.16547_rev1" was uploaded on August 18, 2005.

Many thanks for your support and attention in all matters.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories