




Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:42:19


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:12:24


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:41:12


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:13:03


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 13:38:19


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:58:01


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:17:54


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 11:28:54


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 10:46:24


TEST MODE 4

(Without 10 MHz Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:39:27


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:09:23


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:37:59


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:10:00


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 13:35:25


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:54:39


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:15:09


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 11:25:11


TEST MODE 5

(Without Satellite Reception)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 10:43:36

TEST MODE 5

(Without Satellite Reception)