



FCC TEST ABOUT 9805 ANTENNA

The antenna screw of 9805 is of $M4.0 \times 0.70$ specifications, This specification of the antenna screw is different from the common specifications found in the market $M2.5 \times 0.45$ and $M3 \times 0.5$, which are incompatible.

The antenna fixing nut in the 9805 transmitter is of $M4.0 \times 0.70$ specifications. This specification of the transmitter's nut is different from the common specification found in the market $M2.5 \times 0.45$ and $M3 \times 0.5$, which are incompatible.



**9805 USING
ANTENNA**



**COMMON
ANTENNA**



**COMMON
ANTENNA**