



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 29, 2004

RE: FCC ID: OU4-XSC501_ATCB001071

Attention: Mike Royer

I have a few comments on this Application.

1. Please note that the operational description has three duplicated pages. Please provide only one operational description and remove the duplicated pages.
2. Please note that your manual Class B statement says, "shielded cables must be used with this equipment". What shielded cables are you talking about? Please provide a correct statement for the device in question.
3. Please note that you have provided the OATS setup photos along with the external photos. Please separate the external photos of the device from the OATS setup photos.
4. Please note that the setup photos provided show the device tested inside in close proximity to a number of metal objects that could affect the emissions of this device. Please explain.
5. Please note that this device appears to be able to be installed in at least two of three orthogonal planes, yet was tested in only on plane. Please test the device in all three orthogonal planes.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.