

Marianne Bosley

To: alice_wong@hkstc.com

Subject: Kolara Ind Ltd FCC ID P5H67411009002 Met #11734

Hi Alice,

Below is the technical issue that has arisen from the technical review by the engineer:

1. The bandwidth plot that was submitted does not clearly demonstrate compliance with Section 15.235(b). Please re-plot the emission, with a span of 100 kHz, centered on 49.86 MHz, and use a RBW = 1 kHz, and submit the new plot.

Please forward this data and then we can continue with the Grant. Thank you.

Also, The P5H67411009001 will be Granted soon. It is ready, however, I am encountering a problem with the FCC database. I have contacted them about it, and as soon as it is resolved, I will grant and send it to you.

I will be waiting for the 9002 data. Have a good day.

Marianne T. Bosley

EMC Administrator

410-354-3300, ext. 412