

INTERTEK TESTING SERVICES

Report No.: 031886
Model No.: #10749

Pursuant to FCC Part 15 Section 15.217 Emissions Requirement


DLT: 35.64ms

0.00dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kerell Wong)

Date: 21/7/03

Checked By: [Signature]
(Anthony Chan)

Date: 25/7/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 90ms

F: 27.145400MHz

INTERTEK TESTING SERVICES

Report No.: 0311886
Model No.: #10749

Pursuant to FCC Part 15 Section 15. 7C Emissions Requirement


PLT: 35.70ms

0.00dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: LK
(Kenny Wong)

Date: 2/17/03

Checked By: [Signature]
(Anthony Chan)

Date: 2/17/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 50ms

F: 27.145400MHz

INTERTEK TESTING SERVICES

Report No.: 0311886
Model No.: #10749

Pursuant to FCC Part 15 Section 15.217 Emissions Requirement


DLT: 1.40ms

-0.08dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 50ms

F: 27.145400MHz

Tested By: KK
(Kenneth Wong)

Date: 21/7/03

Checked By: Anthony Chan

Date: 25/7/03

Test Result: Pass / Fail / NA

Report No.: 0511886
Model No.: #10749

Pursuant to FCC Part 15 Section 15. 22X Emissions Requirement


PLT: 300us

-0.02dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: LA
(Vane Wong)

Date: 21/7/05

Checked By: [Signature]
(Anthony Chai)

Date: 25/7/05

Test Result: Pass / Fail NA

DT: 0us

TS: 50ms

F: 27.145400MHz