







DL_869-894_AWGN_894.1-4000MHz_LC




DL_869-894_AWGN_894.1-4000MHz_MC




DL_869-894_AWGN_1000- 4000MHz_HC




DL_869-894_AWGN_4000- 8000MHz_LC




DL_869-894_AWGN_4000- 8000MHz_MC




DL_869-894_AWGN_4000- 8000MHz_HC




DL_869-894_AWGN_8000- 12000MHz_LC




DL_869-894_AWGN_8000- 12000MHz_MC




DL_869-894_AWGN_8000-12000MHz_HC




DL_1930-1995_AWGN_30-1929MHz_LC




DL_1930-1995_AWGN_30- 1929MHz_MC




DL_1930-1995_AWGN_30- 1929MHz_HC




DL_1930-1995_AWGN_1996-4000MHz_LC




DL_1930-1995_AWGN_1996-4000MHz_MC




DL_1930-1995_AWGN_1996- 4000MHz_HC




DL_1930-1995_AWGN_ 4000- 8000MHz_LC




DL_1930-1995_AWGN_4000- 8000MHz_MC




DL_1930-1995_AWGN_4000- 8000MHz_HC




DL_1930-1995_AWGN_ 8000- 12000MHz_LC




DL_1930-1995_AWGN_ 8000- 12000MHz_MC




DL_1930-1995_AWGN_8000- 12000MHz_HC




DL_1930-1995_AWGN_12000- 16000MHz_LC




DL_1930-1995_AWGN_12000- 16000MHz_MC




DL_1930-1995_AWGN_12000- 16000MHz_HC




DL_1930-1995_AWGN_16000-20000MHz_LC




DL_1930-1995_AWGN_16000-20000MHz_MC




DL_1930-1995_AWGN_16000-20000MHz_HC




DL_2110-2155_AWGN_30-2109MHz_LC




DL_2110-2155_AWGN_30- 2109MHz_MC




DL_2110-2155_AWGN_30- 2109MHz_HC




DL_2110-2155_AWGN_2181- 4000MHz_LC




DL_2110-2155_AWGN_2181- 4000MHz_MC




CSE_DL_2110-2155_AWGN_2181-4000MHz_HC




DL_2110-2155_AWGN_4000-8000MHz_LC




DL_2110-2155_AWGN_4000- 8000MHz_MC




DL_2110-2155_AWGN_4000- 8000MHz_HC




DL_2110-2155_AWGN_8000- 12000MHz_LC




DL_2110-2155_AWGN_8000- 12000MHz_MC




DL_2110-2155_AWGN_ 8000- 12000MHz_HC




DL_2110-2155_AWGN_ 12000- 16000MHz_LC




DL_2110-2155_AWGN_12000- 16000MHz_MC




DL_2110-2155_AWGN_12000- 16000MHz_HC




DL_2110-2155_AWGN_16000-20000MHz_LC




DL_2110-2155_AWGN_16000-20000MHz_MC




DL_2110-2155_AWGN_16000- 20000MHz_HC




DL_2110-2155_AWGN_20000- 22000MHz_LC




DL_2110-2155_AWGN_20000-22000MHz_MC




DL_2110-2155_AWGN_20000-22000MHz_HC




DL_2350-2360_AWGN_30- 2349MHz_LC




DL_2350-2360_AWGN_30- 2349MHz_MC




DL_2350-2360_AWGN_30- 2349MHz_HC




DL_2350-2360_AWGN_ 2361- 4000MHz_LC




DL_2350-2360_AWGN_2361- 4000MHz_MC




DL_2350-2360_AWGN_2361- 4000MHz_HC




DL_2350-2360_AWGN_4000- 8000MHz_LC




DL_2350-2360_AWGN_4000- 8000MHz_MC




DL_2350-2360_AWGN_4000- 8000MHz_HC




DL_2350-2360_AWGN_8000- 12000MHz_LC




DL_2350-2360_AWGN_8000-12000MHz_MC




DL_2350-2360_AWGN_8000-12000MHz_HC




DL_2350-2360_AWGN_12000-16000MHz_LC




DL_2350-2360_AWGN_12000-16000MHz_MC




DL_2350-2360_AWGN_12000- 16000MHz_HC




DL_2350-2360_AWGN_16000- 20000MHz_LC




DL_2350-2360_AWGN_16000- 20000MHz_MC




DL_2350-2360_AWGN_16000- 20000MHz_HC



DL_2350-2360_AWGN_20000-24000MHz_LC




DL_2350-2360_AWGN_20000-24000MHz_MC




DL_2350-2360_AWGN_20000- 24000MHz_HC


GSM




UL_663-698_GSM_30- 662.9MHz_LC




UL_663-698_GSM_30- 662.9MHz_MC




UL_663-698_GSM_30- 662.9MHz_HC




UL_663-698_GSM_698.1- 1000MHz_HC




UL_663-698_GSM_698.1- 4000MHz_LC




UL_663-698_GSM_698.1- 4000MHz_MC




UL_663-698_GSM_1000- 4000MHz_HC




UL_663-698_GSM_4000- 8000MHz_LC




UL_663-698_GSM_4000-8000MHz_MC




UL_663-698_GSM_4000-8000MHz_HC




UL_698-716_GSM_30- 697.9MHz_LC




UL_698-716_GSM_30- 697.9MHz_MC




UL_698-716_GSM_30- 697.9MHz_HC




UL_698-716_GSM_716.1- 1000MHz_HC




UL_698-716_GSM_716.1- 4000MHz_LC




UL_698-716_GSM_716.1- 4000MHz_MC




UL_698-716_GSM_1000- 4000MHz_HC




UL_698-716_GSM_4000- 8000MHz_LC




UL_698-716_GSM_4000-8000MHz_MC




UL_698-716_GSM_4000-8000MHz_HC




UL_776-787_GSM_30- 775.9MHz_LC




UL_776-787_GSM_30- 775.9MHz_MC




UL_776-787_GSM_30-775.9MHz_HC




UL_776-787_GSM_787.1-1000MHz_HC



UL_776-787_GSM_787.1- 4000MHz_LC




UL_776-787_GSM_787.1- 4000MHz_MC




UL_776-787_GSM_1000- 4000MHz_HC




UL_776-787_GSM_1559- 1610MHz_LC




UL_776-787_GSM_1559-1610MHz_MC




UL_776-787_GSM_1559-1610MHz_HC




UL_776-787_GSM_4000-8000MHz_LC




UL_776-787_GSM_4000-8000MHz_MC




UL_776-787_GSM_4000- 8000MHz_HC




UL_824-849_GSM_30- 823.9MHz_LC




UL_824-849_GSM_30- 823.9MHz_MC




UL_824-849_GSM_30- 823.9MHz_HC




UL_824-849_GSM_849.1- 1000MHz_HC




UL_824-849_GSM_849.1- 4000MHz_LC




UL_824-849_GSM_849.1- 4000MHz_MC




UL_824-849_GSM_1000- 4000MHz_HC




UL_824-849_GSM_4000-8000MHz_LC




UL_824-849_GSM_4000-8000MHz_MC




UL_824-849_GSM_4000- 8000MHz_HC




UL_824-849_GSM_8000- 12000MHz_LC




UL_824-849_GSM_8000-12000MHz_MC




UL_824-849_GSM_8000-12000MHz_HC




UL_1710-1755_GSM_30-1709MHz_LC




UL_1710-1755_GSM_30-1709MHz_MC




UL_1710-1755_GSM_30- 1709MHz_HC




UL_1710-1755_GSM_1756- 4000MHz_LC




UL_1710-1755_GSM_1756- 4000MHz_MC




UL_1710-1755_GSM_1756- 4000MHz_HC




UL_1710-1755_GSM_4000- 8000MHz_LC




UL_1710-1755_GSM_4000- 8000MHz_MC




UL_1710-1755_GSM_4000-8000MHz_HC




UL_1710-1755_GSM_8000-12000MHz_LC




UL_1710-1755_GSM_8000-12000MHz_MC




UL_1710-1755_GSM_8000-12000MHz_HC




UL_1710-1755_GSM_12000- 16000MHz_LC




UL_1710-1755_GSM_12000- 16000MHz_MC




UL_1710-1755_GSM_12000- 16000MHz_HC




UL_1710-1755_GSM_16000- 20000MHz_LC




UL_1710-1755_GSM_16000-20000MHz_MC




UL_1710-1755_GSM_16000-20000MHz_HC




UL_1850-1915_GSM_30-1849MHz_LC




UL_1850-1915_GSM_30-1849MHz_MC




UL_1850-1915_GSM_30-1849MHz_HC




UL_1850-1915_GSM_1916-4000MHz_LC




UL_1850-1915_GSM_1916- 4000MHz_MC




UL_1850-1915_GSM_1916- 4000MHz_HC




UL_1850-1915_GSM_4000-8000MHz_LC




UL_1850-1915_GSM_4000-8000MHz_MC




UL_1850-1915_GSM_4000-8000MHz_HC




UL_1850-1915_GSM_8000-12000MHz_LC




UL_1850-1915_GSM_8000-12000MHz_MC




UL_1850-1915_GSM_8000-12000MHz_HC




UL_1850-1915_GSM_12000- 16000MHz_LC




UL_1850-1915_GSM_12000- 16000MHz_MC




UL_1850-1915_GSM_12000- 16000MHz_HC




UL_1850-1915_GSM_16000- 20000MHz_LC




UL_1850-1915_GSM_16000-20000MHz_MC




UL_1850-1915_GSM_16000-20000MHz_HC




UL_2305-2315_GSM_30- 2304MHz_LC




UL_2305-2315_GSM_30- 2304MHz_MC




UL_2305-2315_GSM_30- 2304MHz_HC




UL_2305-2315_GSM_2316- 4000MHz_LC




UL_2305-2315_GSM_2316- 4000MHz_MC




UL_2305-2315_GSM_2316- 4000MHz_HC




UL_2305-2315_GSM_4000- 8000MHz_LC




UL_2305-2315_GSM_4000- 8000MHz_MC




UL_2305-2315_GSM_4000-8000MHz_HC




UL_2305-2315_GSM_8000-12000MHz_LC




UL_2305-2315_GSM_8000-12000MHz_MC




UL_2305-2315_GSM_8000-12000MHz_HC




UL_2305-2315_GSM_12000- 16000MHz_LC




UL_2305-2315_GSM_12000- 16000MHz_MC




UL_2305-2315_GSM_12000- 16000MHz_HC




UL_2305-2315_GSM_16000- 20000MHz_LC




UL_2305-2315_GSM_16000-20000MHz_MC




UL_2305-2315_GSM_16000-20000MHz_HC




UL_2305-2315_GSM_20000-24000MHz_LC




3.6.3 CSE_UL_2305-2315_GSM_20000-24000MHz_MC




UL_2305-2315_GSM_20000-24000MHz_HC




DL_617-652_GSM_30-616.9MHz_LC




DL_617-652_GSM_30- 616.9MHz_MC




DL_617-652_GSM_30- 616.9MHz_HC




DL_617-652_GSM_652.1- 4000MHz_LC




DL_617-652_GSM_652.1- 4000MHz_MC




DL_617-652_GSM_ 652.1- 1000MHz_HC




DL_617-652_GSM_ 1000- 4000MHz_HC




DL_617-652_GSM_4000-8000MHz_LC




DL_617-652_GSM_4000-8000MHz_MC




DL_617-652_GSM_4000- 8000MHz_HC




DL_728-746_GSM_30- 727.9MHz_LC




DL_728-746_GSM_30- 727.9MHz_MC




DL_728-746_GSM_30- 727.9MHz_HC




DL_728-746_GSM_746.1- 4000MHz_LC




DL_728-746_GSM_746.1- 4000MHz_MC




DL_728-746_GSM_746.1- 1000MHz_HC




DL_728-746_GSM_1000- 4000MHz_HC




DL_728-746_GSM_4000-8000MHz_LC




DL_728-746_GSM_4000-8000MHz_MC




DL_728-746_GSM_4000- 8000MHz_HC




DL_746-757_GSM_30- 745.9MHz_LC




DL_746-757_GSM_30-745.9MHz_MC




DL_746-757_GSM_30-745.9MHz_HC




DL_746-757_GSM_757.1- 1000MHz_HC




DL_746-757_GSM_757.1- 4000MHz_LC




DL_746-757_GSM_757.1-4000MHz_MC




DL_746-757_GSM_1000-4000MHz_HC




DL_746-757_GSM_4000-8000MHz_LC




DL_746-757_GSM_4000-8000MHz_MC




DL_746-757_GSM_4000- 8000MHz_HC




DL_869-894_GSM_30- 868.9MHz_LC




DL_869-894_GSM_30- 868.9MHz_MC




DL_869-894_GSM_30- 868.9MHz_HC




DL_869-894_GSM_ 894.1- 1000MHz_HC




DL_869-894_GSM_ 894.1- 4000MHz_LC




DL_869-894_GSM_894.1- 4000MHz_MC




DL_869-894_GSM_1000- 4000MHz_HC




DL_869-894_GSM_4000-8000MHz_LC




DL_869-894_GSM_4000-8000MHz_MC




DL_869-894_GSM_4000- 8000MHz_HC




DL_869-894_GSM_8000- 12000MHz_LC




DL_869-894_GSM_8000-12000MHz_MC




DL_869-894_GSM_8000-12000MHz_HC




DL_1930-1995_GSM_30-1929MHz_LC




DL_1930-1995_GSM_30-1929MHz_MC




DL_1930-1995_GSM_ 30- 1929MHz_HC



DL_1930-1995_GSM_ 1996- 4000MHz_LC



DL_1930-1995_GSM_1996-4000MHz_MC



DL_1930-1995_GSM_1996-4000MHz_HC