



Finished Label with Serial Number
and Data Matrix Code Example



Label Die Drawing




Printing Instructions:

Artwork is drawn to scale.

Serial numbers to begin with **2000**
Serial numbers to increment by one for each label
(for example, 1st label serial number is 2000,
2nd label serial number is 2001, etc.)
Bar code to be DataMatrix format

Artwork



DataMatrix Code Instructions:

Data encoded in DataMatrix code to be the following:

Example: V029791;2000

V029791;2000	
This portion will not change. The data in this portion must be included in every DataMatrix code.	This portion is the serial number. It MUST increment and exactly match the serial number printed on each label.

Refer artwork questions to:
Gary Olsen
VPI Engineering
801-495-2310
garyo@vpieng.com

		Drawn	Date	TITLE: WOFS Transmitter Serial Number Label	
		Cog E			
11814 South Election Rd Ste 200 Draper, UT 84020		PH# (801) 495-2310 FAX# (801) 495-2255		DWG. NO. V029809	
				REV 05	
				SCALE: 1:1	
				SHEET 1 OF 1	