


Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)



INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Let and Right Channel)



(Internal)



Equipment Photographs

Model : Podz BL520 (Let and Right Channel)



(Internal)



Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Let and Right Channel)

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Left Channel)

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Left Channel)

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Left Channel)

(Internal)




INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Right Channel)

(Internal)





INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Right Channel)

(Internal)



INTERTEK TESTING SERVICE

Report No.: 0606074

Equipment Photographs

Model : Podz BL520 (Right Channel)

(Internal)

